Index

A	CAT	Pages No.
Alignment system	E	113 to 115
Angle plate	E	90

B		
Balance	E	100 - 101
Battery tester	E	102
Beam trommel	E	44
Bearing checker	E	112
Blade (precision)	E	62
Bore gauge set	E	32

C		
Calipers	E	1 to 7
Centre square	E	56
Checker (bearing)	E	112
Clamp-on multimeter	E	105 - 106
Combination square	E	57
Concentricity test bench	E	94
Counter	E	95 - 96

D		
Depth gauge	E	9
Depth micrometer	E	18
Detector (wood, metal)	E	102
Dial caliper gauge	E	37 to 41
Dial calipers	E	3
Dial gauge	E	25 to 32
Dial gauge stand	E	33 - 34
Digital calipers	E	3 to 7
Divider	E	58

E		
Edges	E	90

F		
Feeler gauge	E	61 - 62
Filetor	E	60
Flange square	E	53
Folding rules	E	49

G		
Gauge (block set)	E	70 to 74
Gauge (depth)	E	9
Gauge (dial)	E	25 to 32
Gauge (feeler)	E	61 - 62
Gauge (height)	E	43
Gauge (plug - snap - thread - taper)	E	63 to 69
Gauge (quick thickness)	E	35 to 41
Gauge (small)	E	60
Gauge (steel marking)	E	44
Gauge (surface)	E	43
Gauge (test)	E	75
Gauge (thread feeler)	E	44
Granite surface plate	E	91 to 93

H

Handtimer	E	98
Hardness tester	E	99
Heigh gauge	E	43

I

Inside micrometer	E	19 to 24
Installation tester	E	108
Insulation tester	E	107

L

Laser distance meter	E	50
Level	E	88 - 89
Lightmeter	E	103
Linear scale	E	84 - 85

M

Magnifiers	E	76 to 79
Marking caliper	E	44
Marking gauge	E	44
Measuring tapes	E	48 to 52
Micrometer	E	8 - 10 to 24
Microscope	E	80 to 82
Multimeter	E	104 to 107 - 109

O

Optical parallel	E	17
Outside micrometer	E	8 to 17

P

Plate (surface)	E	90
Plug gauge	E	63 to 69
Precision blade	E	62
Profile projector	E	83
Protactor	E	59

Q

Quick thickness gauge	E	35 to 41

R

Radius gauge	E	60
Rules	E	46 - 47
Rules (granite)	E	93

S

Scales	E	100 - 101
Scale (linear)	E	84 - 85
Scribers	E	59
Small gauges	E	60
Socket tester	E	102
Sound level meter	E	103
Spring balance	E	100
Squares	E	53 to 57
Squares (granite)	E	92
Stand for dial gauge	E	33 - 34
Steel rules	E	46 - 47
Stopper	E	98
Stopwatches	E	98
Stroboscope	E	97
Surface gauge	E	43
Surface plates	E	90 - 91 - 94
Surface roughness tester	E	86 - 87

T

Tachometer	E	95 - 96
Taper gauge	E	60
Tapes	E	48 to 52
Telescometer	E	51
Test gauge	E	75
Tester	E	102 to 115
Tester (battery)	E	102
Tester (earth - resistivity)	E	111
Tester (installation)	E	108
Tester (insulation)	E	107
Tester (socket)	E	102
Tester (surface roughness)	E	86 - 87
Thermometer	E	103 - 110
Thread feeler gauge	E	44
Thread gauge	E	60
Three point micrometer	E	20 to 24
Trommels	E	44
Twist drill gauge	E	60

V

V-block	E	45
Vernier caliper	E	1 to 7
Vice (precision tools)	E	45
Voltage tester	E	102
V-prismissis (granite)	E	93

W

Weld gauge	E	60
Wire gauge	E	60